





**PAGER** Version 4

Created: 1 day, 4 hours after earthquake


10,000


100,000


1,000

# M 5.8, 130km WSW of Vaini, Tonga

Origin Time: 2019-05-30 15:38:00 UTC (Thu 03:38:00 local) Location: 21.7703° S 176.3071° W Depth: 168.9 km








**Estimated Population Exposed to Earthquake Shaking** 

ESTIMATED POPULATION EXPOSURE (k=x1000)		_*	_*	9k	0	0	0	0	0	0
ESTIMATED MODIFIED MERCALLI INTENSITY		I	11-111	IV	V	VI	VII	VIII	IX	X+
PERCEIVED SHAKING		Not felt	Weak	Light	Moderate	Strong	Very Strong	Severe	Violent	Extreme
POTENTIAL DAMAGE	Resistant Structures	None	None	None	V. Light	Light	Moderate	Mod./Heavy	Heavy	V. Heavy
	Vulnerable Structures	None	None	None	Light	Moderate	Mod./Heavy	Heavy	V. Heavy	V. Heavy

<sup>\*</sup>Estimated exposure only includes population within the map area.

## Population Exposure

population per 1 sq. km from Landscan 5000



#### **Structures**

Overall, the population in this region resides in structures that are highly vulnerable to earthquake shaking, though some resistant structures exist. The predominant vulnerable building types are unknown/miscellaneous types and wood construction.

### **Historical Earthquakes**

Date	Dist.	Mag.	Max	Shaking	
(UTC)	(km)		MMI(#)	Deaths	
1977-06-22	138	8.0	VII(47k)	0	
1983-03-21	109	6.7	VII(53k)	_	
2006-05-03	291	8.0	VIII(7k)	0	

#### Selected City Exposure

from GeoNames.org

MMI City **Population** 

PAGER content is automatically generated, and only considers losses due to structural damage.